



Well was not approved, Therefore,
was never drilled.



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office UtahLease No. U-015473

Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 4 is located 660 ft. from S line and 660 ft. from E line of sec. 19
Center Saline, Sec. 19, (Town 37 S., Range 25 E., Salt Lake
Wildcat (Field) (County Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5127 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)

Morrison Oil Test

150 ft. - 24/ - 8 5/8" casing - cement with 100 sacks cement circulate to surface.

Top Dakota Sand 2272 ft.

Top Morrison Sand 2371 ft.

Top Salt Wash Sand 2710 ft. approximate T. D. 2890 ft.

Run 5 1/2" - 14/ casing to T. D. to be cemented with sufficient cement to bring cement above Dakota Sand.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Harry RoystarAddress 226 Patterson Bldg.Denver, Colo.Royal Hotel, Grand Junction, Colo.By Harry RoystarTitle Operator